


| | | |
|---|--|---------------|
|  | Product Support Engineering Field Service Notification | |
| | Apr 24, 2015 | FSN 15-05-002 |

TITLE OF NOTIFICATION: Verix V/Verix eVo Windows USB Driver v1.0.0.61 Build 2 Release

NOTIFICATION SUMMARY:

This FSN details enhancements and corrections in Verix V/eVo Windows USB Driver version 1.0.0.61 Build 2 since version 1.0.0.57 Build 3. Vx USB Driver version 1.0.0.61 is available for download from DevNet.

See the Notification Text for full details.

TYPE OF NOTIFICATION:

Information/ Programming Notes.

APPLIES TO:

Verix V and Verix eVo platform terminals and PIN Pads.

IMPLEMENTATION NOTES:

Certified for Windows XP (32 and 64 bits), Windows 7 (32 and 64 bits), Windows 8 (32 and 64 bits), Win Server 2003, POSReady 2009, POSReady 7 (32bit & 64bit).

REFERENCES:

Verix V/Verix eVo Windows USB Driver v1.0.0.61 Build 2 Release Notes.

NOTIFICATION TEXT:

Verix V/Verix eVo Windows USB Driver version 1.0.0.61 Build 2 contains the following significant corrections, changes, and enhancements:

1. Corrected a communication problem with using the Echoport application in PosReady 2009.
2. Resolved an issue where device manager hangs after multiple unplug and insertions of the terminal.
3. Corrected a communication issue that resulted in BSOD when using Docklight diagnostic application.
4. Resolved an issue where the PC runs out of memory during VATS endurance tests.

<END>

CONFIDENTIAL INFORMATION: This document contains confidential information that is the property of VeriFone Inc. No part of this document may be copied, distributed, stored in a retrieval system, translated into any human or computer language, or transmitted in any form or by any means, without the prior written consent of VeriFone.